

January, 2023

Explained why we thought the exceedence occurred. Installed "Tee's" on discharge pipes.

44691 Rocky Fork Unsatisfactory Findings

Finding #1, Not properly re-weighting the TSS pans as stated in Method 2540D
Finding #2, Failed to perform GGA checks during BOD analysis.
No Response Required, issues have been corrected.

44725 South Rte K lagoon Letter of Warning

Lagoon exceeded pH limit of 9.0 during 2nd Quarters of 2021 and 2022
Plan to monitor pH closely during algae growth and cease discharge if possible